



RELEASE NOTES

AOS version R10.9.1
October 21, 2013

Trademarks

Any brand names and product names included in this manual are trademarks, registered trademarks, or trade names of their respective holders.

To the Holder of the Manual

The contents of this manual are current as of the date of publication. ADTRAN reserves the right to change the contents without prior notice.

In no event will ADTRAN be liable for any special, incidental, or consequential damages or for commercial losses even if ADTRAN has been advised thereof as a result of issue of this publication.

Toll Fraud Liability

Be advised that certain security risks are inherent in the use of any telecommunications or networking equipment, including but not limited to, toll fraud, Denial of Service (DoS) attacks, loss or theft of data, and the unauthorized or illegal use of said equipment. ADTRAN OFFERS NO WARRANTIES, EITHER EXPRESSED OR IMPLIED, REGARDING THE PREVENTION, DETECTION, OR DETERRENCE OF TOLL FRAUD, NETWORKING ATTACKS, OR UNAUTHORIZED, ILLEGAL, OR IMPROPER USE OF ADTRAN EQUIPMENT OR SOFTWARE. THEREFORE, ADTRAN IS NOT LIABLE FOR ANY LOSSES OR DAMAGES RESULTING FROM SUCH FRAUD, ATTACK, OR IMPROPER USE, INCLUDING, BUT NOT LIMITED TO, HUMAN AND DATA PRIVACY, INTELLECTUAL PROPERTY, MATERIAL ASSETS, FINANCIAL RESOURCES, LABOR AND LEGAL COSTS. Ultimately, the responsibility for securing your telecommunication and networking equipment rests with you, and you are encouraged to review documentation regarding available security measures, their configuration and implementation, and to test such features as is necessary for your network.

ADTRAN Technical Support Community

For information on installing and configuring ADTRAN products, visit the ADTRAN Support Community, <https://supportforums.adtran.com>.



Pre-Sales Technical Support
(800) 615-1176
application.engineer@adtran.com

Corporate Office
901 Explorer Boulevard
P.O. Box 140000
Huntsville, AL 35814-4000
Phone: (256) 963-8000
www.adtran.com

Post-Sales Technical Support
(888) 423-8726
support@adtran.com

Copyright © 2013 ADTRAN, Inc.
All Rights Reserved.

Contents

<i>Introduction</i>	4
<i>Supported Platforms</i>	4
<i>System Notes</i>	5
<i>Features and Enhancements</i>	5
<i>Fixes</i>	6
<i>Errata</i>	7
<i>Upgrade Instructions</i>	14
<i>Documentation Updates</i>	14

Introduction

AOS version R10.9.1 is a maintenance release that addresses customer issues that were uncovered in previous code releases.

This release is generally available code. Results obtained during internal testing have been evaluated and the code has been determined to be ready for general availability. Caveats discovered during testing but not addressed in this build are listed in *Errata on page 7*.

A list of new or updated documents for this release appears in *Documentation Updates on page 14*.

Configuration guides, white papers, data sheets, and other documentation can be found on ADTRAN's Support Forum, <https://supportforums.adtran.com>. The contents of these release notes will focus on the platforms listed below.

Supported Platforms

The following platforms are supported in AOS version R10.9.1. To confirm the Boot ROM version of the ADTRAN unit, Telnet or console to the unit and issue the **show version** command. In the command output, the Boot ROM version will be listed as **Boot ROM version XX.XX.XX**. If you require a Boot ROM upgrade, please contact ADTRAN Technical Support (support@adtran.com or 888-423-8726) for assistance.

Platform	Standard Feature Pack	Enhanced Feature Pack	SBC Feature Pack	Minimum Boot ROM
NetVanta 644		√		A5.01.B1
NetVanta 1234/1234P (2nd Gen. only)	√			XB.01.02
NetVanta 1238/1238P (2nd Gen. only)	√			XB.01.02
NetVanta 1534	√			17.06.03.00
NetVanta 1534 (2nd Gen.)	√			17.08.01.00
NetVanta 1534P (2nd Gen.)	√			17.09.01.00
NetVanta 1535P	√			17.08.01.00
NetVanta 1544/1544F	√			17.06.03.00
NetVanta 1544 (2nd Gen.)	√			17.08.01.00
NetVanta 1544P (2nd Gen.)	√			17.09.01.00
NetVanta 1638	√			18.02.01.SC
NetVanta 1638P	√			18.02.01.SC
NetVanta 1335		√		15.01.00
NetVanta 3120		√		14.04.00
NetVanta 3130		√		14.04.00
NetVanta 3200/3205 (3rd Gen. only)	√	√		17.02.01.00
NetVanta 3305 (2nd Gen. only)	√	√		04.02.00
NetVanta 3430	√	√		13.03.SB
NetVanta 3430 (2nd Gen.)	√	√	√	17.05.01.00
NetVanta 3448	√	√	√	13.03.SB
NetVanta 3450	√	√		17.06.01.00

Platform	Standard Feature Pack	Enhanced Feature Pack	SBC Feature Pack	Minimum Boot ROM
NetVanta 3458	√	√		17.06.01.00
NetVanta 4305 (2nd Gen. only)	√	√		08.01.00
NetVanta 4430	√	√	√	17.04.01.00
NetVanta 5305	√	√		11.03.00
NetVanta 6240		√	√	A5.01.00
NetVanta 6250		√	√	R10.9.0
NetVanta 6355		√	√	A2.06.B1
Total Access 900 Series (2nd Gen. only)		√		14.04.00
Total Access 900e Series (2nd Gen. only)		√	√	14.05.00.SA
Total Access 900e Series (3rd Gen. only)		√	√	R10.9.0

System Notes

- Beginning with AOS version 17.09.01, the syntax of certain commands was modified from previous AOS versions by either removing or adding the **ip** keyword. In general, when the **ip** keyword appears in a command, it signifies that the command is only applicable to IPv4 functionality. As more features introduce IPv6 support, the **ipv6** keyword is added to signify the command is only applicable to IPv6 functionality. The **ip** keyword has been removed from several commands to signify that the command has both IPv4 and IPv6 functionality.

Due to this syntax change, downgrading a unit configured in AOS version R10.9.1 to a previous AOS version, could cause service disruption because the new syntax might not be recognized by the previous version. Upgrading a unit from an older AOS version to AOS version R10.9.1 will cause no service disruption because both the old and the new syntaxes are accepted. For more information on specific commands, refer to the [AOS Command Reference Guide](https://supportforums.adtran.com) available at <https://supportforums.adtran.com>.

- It is recommended that your browser's cache be cleared before viewing the GUI after an upgrade.

Features and Enhancements

This section highlights the voice specific features, commands, and behavioral changes in products running AOS version R10.9.1

- Added the ability to configure SIP Timers D & J, which affects how long a SIP transaction resource is reserved once the final message in a transaction is received.

This section highlights the major features, commands, and behavioral changes for all Converged Access products running AOS version R10.9.0.

- Added support for the NetVanta 6250 series.
- Added support for the third generation Total Access 900e series.
- Added support for 10 individual port channels in an ActivChassis configuration. Prior to this release, an ActivChassis configuration only supported 6 port-channels.
- Added support for IPv6 DHCP client capabilities.
- Added support for the use of named prefixes for management of IPv6 prefixes.

- Added support for the NetVanta 1131 Redundant Power Supply/Extended Power Supply (RPS/EPS) for NetVanta 1500 Series and NetVanta 1638 Series switches in ActivChassis mode.

This section highlights the voice specific features, commands, and behavioral changes available in products running AOS version R10.9.0.

- Added SIP proxy monitor to the SIP proxy rollover functionality. When the SIP proxy is in monitored rollover mode, the SIP proxy monitor will poll the primary server to detect when it is operational again and it is safe to route traffic to it. Optionally, the SIP proxy monitor can be used to monitor the active server while the proxy is not in rollover mode. This allows the proxy to detect when the server goes down without a call being placed. The SIP proxy monitor is available in stateful proxy mode only.
- Added a SIP monitor rollback timer to the SIP trunk failover functionality. The delay introduced by the rollback timer will prevent a server from being selected while the delay is in effect.

Fixes

This section highlights major bug fixes for all products running AOS version R10.9.1.

- File transfers from an AOS device to nCommand MSP may have failed.
- Syslog output sent for **priority-level info** can eventually cause a memory leak on a NetVanta 1638.
- When polled via SNMP, a Frame Relay subinterface reports an ifSpeed of 0.
- Removing and then adding an NTP server in quick succession can cause a reboot.
- In rare cases, a reboot may have occurred when NTP attempted to synchronize the AOS unit's clock.

This section highlights the voice specific bug fixes in products running AOS version R10.9.1, unless otherwise noted.

- When using ANI/DNIS substitution, it was possible for the unit to reboot in rare cases.
- If a SIP trunk monitor or SIP proxy monitor was enabled, changing the VRF in which the SIP was running caused a reboot.
- During SIP proxy survivability, an IPv6 loopback address was inserted into the SDP of calls routed to SIP proxy users on units running R10.8.0 and later.
- When using the default LBO setting (**lbo long 0**) on a T1 on a 2nd Generation Total Access 900e with the v3.1 T1 framer, it was possible for T1 errors to occur due to the pulse shape being close to out of spec.
- T.38 calls failed if it took longer than 45 seconds to send a page.
- On a SIP-to-SIP call through the B2BUA, if the destination SIP server did not respond to an INVITE, the AOS unit may have sent a 400 Bad Request response to the original INVITE instead of a 503 Service Unavailable response.
- When the hex encoding for # (%23) was received in a SIP URI, it was not properly converted back to # before being processed by the switchboard.
- It was possible to configure the UDP port range for the DSP to overlap with the port range used by RTP Firewall Traversal, which may have caused one-way audio.

Errata

The following is a list of errata that still exist in all products running AOS version R10.9.1.

- DNS queries created by an AOS IPBG might be sent using the DSP port range, which could prevent responses from being properly received.
- Setting a very long description (over 110 characters) on a T1 interface, and then attempting to view the description in the configuration, can cause the AOS unit to reboot.
- Ethernet interfaces in third generation Total Access 900e units are not visible in the Data > IP Interfaces GUI menu. These interfaces are visible and can be configured from the System > Physical Interfaces menu instead.
- The MRRU value in output of the **show interface ppp** command always displays default MRRU of 1520, regardless of what is negotiated between the two PPP peers. This issue is purely cosmetic.
- The GetResponse after an SNMP inform can be rejected causing a retransmission of the inform message.
- Naming a hardware ACL the same name as a previously created and deleted IP ACL will result in the creation of an IP ACL with an implicit permit.
- Configuring a NetVanta 160's channel setting to **least-congested** may not properly adjust to the least congested channel available.
- DNS queries created by an AOS device may be sent using source port UDP 4500, which could prevent responses from being properly received if **ip crypto** is enabled.
- Executing a TCL script that issues the command **show tech** may inhibit the ability to further run **show tech** commands until the AOS device has been rebooted.
- In rare cases, ICMP probes may transmit faster than the configured period.
- The NetVanta 3130 does not include an option in the GUI to select Annex M.
- On layer 3 switches running AOS R10.7.0 and higher, IP Routing cannot be enabled or disabled via the GUI.
- On certain NetVanta routers, it is not possible to remove SNMP users.
- On very rare occasions, port T1 3/3 on an Octal T1 NIM can stop negotiating LCP when it is part of an MLPPP bundle. Rebooting the device will restore the interface.
- On a NetVanta 6310, if a SHDSL circuit with a detected bad splice retrains to a different line rate, the distance of the bad splice will display incorrectly.
- If the top level ATM interface on a SHDSL ATM NIM2 module is disabled and re-enabled, the ATM circuit will no longer be able to pass traffic. The ADTRAN unit must be rebooted to correct the problem.
- The T1 EFM counters do not increment as traffic passes through the device.
- With the SHDSL ATM NIM2, the NetVanta 6310 drops approximately 1 out of every 15K packets from the SHDSL to Ethernet direction.
- Performance throughput for 66 byte packets on the NetVanta 6355 4 T1/NAT test cases has decreased approximately 40 percent. All other packet sizes, including IMIX traffic, have acceptable throughput.
- Removing a USB modem from the USB NIM while active could cause the AOS device to reboot. Shutting down the demand interface being used by the modem prior to removing the modem will prevent this reboot.
- In redundant Ethernet mode, if the Ethernet interface is configured with subinterfaces, the NetVanta 644 will reboot when one of the Ethernet cables is removed.

- Copying a file larger than 20 MB from flash memory of an AOS device via HTTP can cause the AOS device to reboot.
- In rare cases, SFP ports on a NetVanta 1535P could get stuck in an up/up state even when physically disconnected. Shutting down the port and re-enabling it resolves the issue.
- The GUI of a NetVanta device acting as a wireless access controller can not display the software currently running on a connected access point.
- The command **boot config flash** <filename> does not function properly on many AOS platforms.
- A host name entry in an ACL may fail to resolve to the correct IP address even though the router's host table reflects the correct IP address. Workaround: Use IP addresses instead of a host name when creating an ACL.
- In a 3G demand interface configuration, Syslog traffic can intermittently be sourced from an incorrect IP address.
- When command authorization is enabled, issuing a **show** command with the **realtime** parameter does not display the statistics in real time.
- The IP Top Talkers Graphs in the GUI will sometimes truncate IP addresses.
- The **show interface adsl** command is not available in user mode.
- Event messages indicating a firmware upgrade was attempted may appear in the AOS event log for NetVanta 160 APs that are not being upgraded.
- When configured for **terminal length 0** certain **show** commands will not provide complete output.
- The VNS verification process does not remove inconsistent A-type records from the host table after the configured number of attempts.
- Configuring over 1200 VNS entries on the NetVanta 3448 causes a SIP pre-parse error.
- If the **ethernet-cfm** command is configured on a MEF Ethernet interface, the output of the following CLI commands is not formatted properly:
 1. **show ethernet cfm association**
 2. **show ethernet cfm stack**
 3. **show ethernet cfm mep local**
 4. **show ethernet cfm mep local detail**
- Wi-Fi multimedia (WMM), configured with the command **qos-mode wmm**, does not function properly on NetVanta 150 Access Points.
- When configured with two port channels, each with more than two members, one of the port channels may not evenly distribute traffic sent over the aggregated link.
- A NetVanta 1638 may occasionally display the following message on boot: HTTP_CLIENT CONNECT_TO_HTTP_SERVER errorCode 251. This does not cause a functional problem.
- The **called-number** command on a demand interface does not function properly.
- An ActivChassis stack cannot pass a full 10 Gbps of 64-byte frames over a single 10 Gb fiber link in a NetVanta Dual SFP+ XIM.
- It is possible to create a standard MAC ACL with the same name as an existing extended MAC ACL.
- If a line card has the same VCID as another line card, it cannot be added to the ActivChassis stack. The command **show ac detail** does not adequately point out the reason for this failure.

- If there are spanning tree topology changes in the network, spanning tree will reconverge at rates lower than rapid spanning tree (about 30 seconds).
- The NetVanta 1638 cannot boot from a firmware image stored on a connected USB flash drive.
- If an ActivChassis line card has NetVanta APs physically attached and if the line card is removed and re-added to the ActivChassis stack, the NetVanta APs will not properly indicate the AC that is controlling them. Bouncing the switchport on the line card or rebooting the ActivChassis master will resolve this issue.
- When using XAUTH with a VPN client, an AOS device requests CHAP authentication from the client but does not send a CHAP challenge payload. This can cause issues with VPN clients that expect to receive this payload.
- WEP encryption does not function properly on NetVanta 160s.
- Legacy switch stacking can not be configured if VLAN 2386 is created prior to enabling stacking.
- If a USB modem is physically disconnected from a USB WWAN NIM while active NIM is active, the demand interface being used by the modem will not automatically shut down. The demand interface should be disabled before removing the modem to prevent this issue.
- On the NetVanta 6310/6330, with FFE enabled, passing traffic from the Ethernet 0/1 interface out an Ethernet NIM2 can cause the Ethernet 0/1 interface to fail. The interface is recovered with a reboot. Disabling FFE on the Ethernet 0/1 interface prevents the issue.
- An SNMP walk of the NetVanta 6355 lists the physical address for the first interface index only.
- When a switchport on a NetVanta 1535P is running forced speed 100 Mbps in standard mode (not ActivReach mode), jumbo frames greater than 9000 bytes will be dropped.
- The chassis fans in some NetVanta PoE switches oscillate at a higher frequency than expected during periods when the switch is not being heavily utilized.
- The current AOS implementation of DHCP message construction may result in Windows XP machines not adopting the DNS servers defined in the DHCP Offer. A workaround using a numbered IP/hex option will allow the message to be constructed in a manner that Windows XP will accept. Microsoft also offers a hotfix to resolve this Windows issue.
- The system clock may drift and lose synchronization with higher stratum devices when NTP is enabled. This issue only affects the NetVanta 3448, 3458, and 6240 products.
- NetVanta 1500 and NetVanta 1600 Series switches may not properly prioritize traffic across port channels.
- Certain OIDs in the Bridge-MIB may not return a value on a second generation NetVanta 123X switch.
- The Layer 3 switch incorrectly reports forwarded frames statistics when subjected to a traffic stream consisting of invalid IPv4 header checksum values. The frames are properly dropped by the switch, but the statistics counter erroneously reports frames being forwarded
- The **vap-reference** command will not replicate VLAN IDs for an AP unless 802.1q encapsulation has been manually enabled on the AP expecting to receive the replicated configuration.
- Updating PRL values on a Sprint 3G CDMA NIM may not function properly.
- The parent map QoS statistics must be cleared in order to clear the child map statistics.
- A specific QoS map entry cannot be cleared without the entire map being cleared.

- In rare cases, when an IP PBX and IP phones are both passing through a NAT and the SIP proxy on an AOS device, some call flows can enter a one-way-audio state. Enabling the **ip rtp firewall-traversal enforce-symmetric-ip** command from the Global Configuration mode works around the issue.
- A large enough drift in the system clock can cause an error when the NTP server attempts to synchronize.
- On a NetVanta 1335, a switchport that is configured as a port channel cannot change the edge port mode and cannot be changed from a port channel to another configuration using the GUI.
- The **show interfaces** command output for multilink Frame Relay interfaces will display an incorrect available bandwidth value when a physical link residing in the bundle is down.
- When a QoS map is applied to a VLAN interface, the NetVanta 3448 and 3458 platforms fail to reset QoS map statistics after the **clear counters** command is issued. The **clear qos map** command will clear the statistics properly.
- The VLAN ID for an access point cannot be changed using the GUI.
- The **show atm pvc** counters do not increment.
- The **show bridge <number>** command might not show any entries.
- Using SCEP, AOS devices can fail to enroll certificates to a Red Hat Certificate Authority.
- On a NetVanta 1534, if an interface is configured as a port mirror destination (**monitor session 1 destination interface gigabit-switchport <slot/port>**), then port authentication will no longer be configurable on that port, even after removal of the **port mirror** command from the configuration.
- A VLAN interface for a VLAN that is not accessed by other switchports will not be advertised by GVRP.
- The NetVanta 1638 fails to count output discards when throttling down the transmission of traffic (as a result of receiving pause frames).
- The input/output rate counters for a T1 interface are exaggerated for approximately 15 seconds after clearing them.
- The GUI statistics page for the SHDSL interface does not refresh when in 4-wire mode.
- The GUI shows invalid line rate options for a SHDSL interface in 2-wire mode.
- The GUI line rate options for a SHDSL interface do not match those of the CLI.
- Adding an IPv6-enabled PPP interface to a bridge group does not require the user to first remove the IPv6 address from the PPP interface.
- Configuring a port channel on a NetVanta 3448 can cause the STP topology to become unstable.
- Switch platforms count input discards on the ingress interface when receiving 802.3x pause frames.
- Sierra Wireless USB305 3G modems are sometimes not recognized by the USB WWAN NIM.
- Changing the route metric value using **ipv6 address autoconfig default metric <value>** command does not change the administrative distance of the default route.
- The NetVanta 5305 can drop some traffic prioritized by class-based weighted fair queuing (CBWFQ) on a MLPPP interface when a stand-alone QoS map is applied.
- The DNS server can take action on received DNS responses that are not associated with an open request, posing a DoS attack vulnerability.
- A NetVanta 5305 can stop passing traffic for brief intervals when negotiating frequent VPN tunnels using Diffie Hellman Group 5.
- The output queue statistics on an Ethernet interface can fail to display output queue drops when FIFO is enabled.

- Prioritized traffic can be dropped at a significant rate on PPP interfaces when using a parent QoS map (that references a child map with priority allocation), if the shaped rate is configured for more than 75 percent of the line rate.
- The CLI does not display the correct value for Required Bandwidth in the event message generated by applying a QoS map.
- The output from **show qos map interface ppp 1** displays incorrect values for the number of packets sent.
- The NetVanta 5305 can fail to generate an event message to confirm that a QoS map has been applied.
- EAP Identity responses from a wireless client that do not contain an Identity field can result in a malformed RADIUS packet created by the NetVanta 150.
- NetVanta 150s might not properly handle immediate Access-Accept responses to Access-Request messages.
- In certain instances, an SFP port on a NetVanta 1544 will not function with RAD MiRiCi-E3T3 SFPs.
- 3G connections using a NetVanta USB WWAN NIM and a Sierra Lightning modem can fail.
- The name of a deleted IPv4 ACL cannot be used to name a new IPv6 ACL.
- The cellular interface can trigger a core dump on a NetVanta 3448 when changing states.
- Port mirroring on a NetVanta 1544 switch may not mirror traffic in both directions.
- Proxy user templates cannot modify SDP IP addresses correctly in certain applications.
- Browsing to the Switchports menu from the Port Security menu on the NetVanta 1335 WiFi GUI results in a 503 Service Unavailable error.
- Connecting a Novatel U547 USB modem to the NetVanta USB WWAN NIM can cause the router to reboot.
- A startup configuration with greater than 2743 IPv6 prefixes on a VLAN interface causes the NetVanta 3448 to reboot.
- A Spanning Tree L2 broadcast storm lasting several hours can cause the NetVanta 1335 to reboot.
- The L3 Switch Header Error and Discard counters on the NetVanta 1544P (second generation) do not increment.
- The pass phrase for the Wireless Wizard does not persist across reboots.
- Removing and restoring cross-connects multiple times can cause the PC configuration thread depth to reach 100 percent.
- Rapidly removing and adding cross-connects using the CONSOLE port and SSH at the same time can result in a reboot.
- When a switchport on a NetVanta 3458 is configured for **port-security**, it does not receive BPDUs. If multiple connections between the NetVanta 3458 and another switch are made, a switching loop could occur because both ports will automatically enter a forwarding state even though the Spanning Tree protocol should cause one port to enter a blocking state.
- Booting a second generation NetVanta 1534 or NetVanta 1535 with greater than 20 NetVanta 160 Access Points (APs) attached can cause some of the APs to pull incomplete configuration from the NetVanta switch, if they are being used as an access controller for the APs.
- Using the command **debug ethernet cfm loopback request domain <domain name>** to filter Ethernet CFM loopback debugs may not display the debug output to the console. Removing the filter and using the **debug ethernet cfm loopback request** command will function properly.

- The output of the command **show ethernet cfm mep local** may display an incorrect maintenance association for a MEP ID if multiple maintenance associations are configured on the unit.
- The NetVanta 6240 should send warm_start SNMP traps when the unit is told to reboot by software. It should only send cold_start traps when the power is cycled. Instead, it is sending cold_start traps, even when reloaded by software.
- In the VQM RTP Monitoring menu, the Source IPs and Interfaces menus have invisible data points that appear and display data when the cursor hovers over them. The invisible data point information duplicates a visible data point and can usually be found hidden above the visible data point.
- In the VQM RTP Monitoring menu, the refresh button refreshes the displayed graphic, but it also duplicates information in the lower part of the menu. Also, when the cursor hovers over a data point, it displays multiple instances of the same data.

The following is a list of voice specific errata that exist in products running AOS version R10.9.1, unless otherwise noted.

- Call waiting caller ID may not function properly when received via a SIP INFO message instead of a new INVITE.
- On the NetVanta 644, hairpinned TDM calls may not have a talk path.
- In rare cases, the NetVanta 644 may reboot if a PRI interface goes down and then comes back up in quick succession.
- In rare cases, it is possible for B-channel resources to not release properly, preventing the channel from being used.
- In AOS R10.4.0 and higher, modem-passthrough will fail to send a reINVITE to G.711 if the endpoint is configured with a codec-list that doesn't contain G.711.
- When both **g711alaw** and **g711ulaw** are present in a codec-list, G.711u will be chosen by modem-passthrough, even if **g711alaw** is listed higher in the codec-list than **g711ulaw**.
- The GUI should not provide a **Disable** setting for a voice user forward disconnect.
- In the PRI settings, invalid switch type options are presented in the GUI drop-down list.
- When **mwi-member** is configured on a ring group, received NOTIFY messages will not match against SIP identities/aliases configured on the ring group.
- When using **ringback override 180**, it is possible to have one-way or no audio after an inbound call completes due to the AOS device resending stale SDP.
- Invalid characters are allowed in a host name for the SIP server on a voice trunk.
- If a call is ringing due to a SIP 180 response for longer than the value of **ip rtp session timeout** (45 seconds by default), there will be no talk path in the SIP to TDM direction when the call is answered.
- When **voice codec-priority user** is configured, calls to a ring group can result in a less preferable CODEC being selected.
- Local three-way conference calls against a Metaswitch will fail if one of the calls in conference is a hairpin call between two FXS users.
- In the ISDN voice trunk GUI, the **Disabled:Busy on Idle** and **Disabled:Busy Immediately** Administrative Status options do not function.
- If an ADTRAN unit is configured with single call appearance mode, forwarded calls on a PRI trunk will fail.

- Receiving a 183 after a 183 on hairpin calls when using media anchoring could result in no early media if the SDP in the second 183 differs from the first.
- Echo cancellation is not enabled on 3-way calls when using the local conferencing feature.
- AOS does not properly handle more than two Diversion headers that are appended with a comma.
- On NetVanta 6240 Series units, V.21 messages will sound overly amplified when listening to the TX output of a T.38 DSP capture. This is a flaw of the capture utility and not representative of how the audio actually sounds.
- DSP captures on the NetVanta 6240 and NetVanta 644 platforms consume large amounts of memory while in progress. The unit could become unstable if a DSP capture is active for an extended period of time.
- With the AOS unit set for **voice flashhook mode transparent**, the conference originator must wait for the third party to answer before executing the flashhook to initiate the conference.
- On the NetVanta 6240 Series, over an extended period of use, T.38 calls can cause DSP channels to cease producing a dial tone and have poor voice quality. Rebooting the unit will correct the problem.
- NetVanta 6240 only: While running 29 or more simultaneous calls using E&M Immediate, Wink, or Feature Group D, it is possible to get in a state where DTMF tone detection will not function on any outbound (DSX to SIP) call using DSP 0/1.15 or higher. While in this failed state, all calls will continue to function in either call direction on DSP 0/2, as well as all calls on DSP0/1 in the inbound direction. With a load of 28 or less calls, all calls will function reliably in both directions on both DSPs. No consistent work around has been identified at this time. A unit reboot will typically solve the problem.
- The NetVanta 6240 Series IP Business Gateways can reboot if 60 simultaneous calls are placed through the DSP.
- In either the voice trunk or voice user configuration modes where a CODEC list is configured, entering the command **no codec-list** *<list name>* *<direction>* will remove the *<list name>*, no matter which *<direction>* is configured.
- The Total Access 900e Series cannot properly handle more than 40 simultaneous E&M RBS calls. More than 40 simultaneously active calls can result in no dial tone or no audio on the last 8 channels.
- Using the HEAD acoustics test suite, some G.168 echo cancellation test cases fail on the NetVanta 6240 and NetVanta 644. These same tests pass on Total Access 900 Series units. There is no reason to believe this would affect a customer in the field.
- NetVanta 6310/6330 Series platforms only: If a SIP trunk attempts to register a large number of users and the registration fails, activating **debug sip trunk-registration** command will cause the Telnet and console connection to become unresponsive. A reboot clears the condition.

Upgrade Instructions

Upgrading ADTRAN products to the latest version of AOS firmware is explained in detail in the configuration guide *Upgrading Firmware in AOS*, available at <https://supportforums.adtran.com>.

Documentation Updates

The following documents were updated or newly released for AOS version R10.9.1 or later specifically for the AOS products. These documents can be found on ADTRAN's Support Forum available at <https://supportforums.adtran.com>. You can select the hyperlink below to be immediately redirected to the document.

- *AOS Command Reference Guide*
- *Configuring IPv6 in AOS*
- *NetVanta 1131 Redundant/Extended Power Supply Quick Start Guide*
- *NetVanta 6240/6250 Quick Start Guide*