

ADTRAN vWLAN 2.4 Supplemental Patch Bundle Release Notes

Patch Names:

- GarbageCollection-TG7117
- LocationEdit-TG6857
- LogFile-TG7108
- ReplicationPasswordChange-TG7096
- WebRedirectionAcct

vWLAN Version Required: 2.4.0.12 with vPatch-2-4-0-12

Document Date: May 4, 2015

These Release Notes list fixes, known issues, and other important information about this patch developed for vWLAN.

Contents

| | |
|---|---|
| Important Notices | 2 |
| Previous Patches | 2 |
| Patches and High Availability..... | 2 |
| Uninstalling Previous Patches..... | 2 |
| Installing Patches | 2 |
| Fixes..... | 3 |
| GarbageCollection-TG7117 patch | 3 |
| LocationEdit-TG6857 patch | 3 |
| LogFile-TG7108 patch | 3 |
| ReplicationPasswordChange-TG7096 patch..... | 3 |
| WebRedirectionAcct patch..... | 3 |
| Errata..... | 3 |

Important Notices

Previous Patches

This is collection of supplemental patches and does not include fixes from previous patches.

Patches and High Availability

In a high availability network configuration, each vWLAN platform must have patches installed individually (patches are not replicated between the primary and secondary vWLAN instances).

Uninstalling Previous Patches

All previous patches (except for vPatch-2-4-0-12 and Heartbleed-TG5986) will need to be removed prior to installing this patch. Note that a reboot is necessary following the removal of patches.

1. Navigate to the **Administration** tab and select **Patch**
2. Select the patch to delete and click **Delete**.
3. Once the patches have been removed, reboot vWLAN.

Installing Patches

Note that a reboot is necessary following the installation of this patch.

1. Navigate to the **Administration** tab and select **Patch**
2. Select the patch to install using the **Browse** button.
3. Select **Install**.
4. Any patches that you have installed will be visible in the **Patch list**. A **Platform Task** should display stating that a reboot is required.

Fixes

GarbageCollection-TG7117 patch

vWLAN disk utilization could exceed capacity resulting in loss of administrative and user access.

LocationEdit-TG6857 patch

When a Location was modified, the Location Discovery process would not finish until the User Management process was restarted.

LogFile-TG7108 patch

Internal process errors resulted in the Admin UI becoming sluggish.

ReplicationPasswordChange-TG7096 patch

Replication failed when admin updated an account's password with an invalid password (fewer than eight characters).

WebRedirectionAcct patch

This patch includes multiple improvements to the performance of HTTPS redirection processes as well as resolution for a process failure that could occur with RADIUS accounting.

Errata

- RADIUS Accounting doesn't work with Captive Portal Authentication.
- RADIUS Accounting Class attribute is not sent.

Other known issues are outlined in the [vWLAN Version 2.4.0.12 Release Notes](#) and [vPatch-2-4-0-12 Release Notes](#) in the [ADTRAN Support Community](#).