



Q&A

The DTE management DLCI (1007) is not displayed in my router's DLCI list through the FRAD. What should I do?

Q: The DTE management DLCI (1007) is not displayed in my router's DLCI list through the FRAD. What should I do?

A: Verify that the management PVC option is enabled. If it is enabled, try changing the management DLCI to a number between 16 - 990 which is not being used by your Frame Relay provider for your circuits.
